



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Version of phone software used to test/ Comments
1	Nokia	6103	HF	✓	✓	✓	✓	✓	✓	V04.90
2		6131	HF	✓	✓	✓	✓	✓	✓	V03.70
3		6270	HF	✓	✓	✓	✓	✓	✓	V03.66
4		6280	HF	✓	✓	✓	✓	✓	✓	V4.25
5		6288	HF	✓	✓	✓	✓	✓	✓	V05.92
6		6233	HF	✓	✓	✓	✓	✓	✓	V03.70
7		6234	HF	✓	✓	✓	✓	✓	✓	V03.50
8		E50	HF	✓	✓	✓	✓	✓	✓	V06.27.1.0
9		E60	HF	✓	✓	✓	✓	✓	✓	V.0610.02.15
10		E61	HF	✓	✓	✓	✓	✓	✓	V 3.0633.09.04
11		E65	HF	✓	✓	✓	✓	✓	✓	V 1.0633.18.01
12		E70	HF	✓	✓	✓	✓	✓	✓	V1.0610.05.06
13		6300	HF	✓	✓	✓	✓	✓	✓	V 04.70
14		6310	HF	✓	✓	✓	✓	✓	✓	V5.10
15		6310i	HF	✓	✓	✓	✓	✓	✓	V5.51
16		9300	HF	✓	✓	✓	✗	✓	✓	V4.53
17		9300i	HF	✓	✓	✓	✗	✓	✓	V 05.50(00)
18		9500	HF	✓	✓	✓	✗	✓	✓	V4.44
19		6600	HF	✓	✓	✓	✓	✓	✓	V3.42.1
20		3230	HF	✓	✓	✓	✓	✓	✓	V3.0505.2
21		3250	HF	✓	✓	✓	✓	✓	✓	V03.24
22		5500	HF	✓	✓	✓	✓	✓	✓	V 03.18
23		6680	HF	✓	✓	✓	✓	✓	✓	V3.04.11
24		6681	HF	✓	✓	✓	✓	✓	✓	V3.10.6
25		N70	HF	✓	✓	✓	✓	✓	✓	V2.0536.02
26		N71	HF	✓	✓	✓	✓	✓	✓	V 2.0613.1.12.1
27		N73	HF	✓	✓	✓	✓	✓	✓	V2.0628.0.0.1
28		N90	HF	✓	✓	✓	✓	✓	✓	V5.0607.7.3
29		N91	HF	✓	✓	✓	✓	✓	✓	V1.11.003
30		N93	HF	✓	✓	✓	✓	✓	✓	V10.0.025
31		N80	HF	✓	✓	✓	✓	✓	✓	V 3.0617.0.6
32		6630	HF	✓	✓	✓	✓	✓	✓	V2.39.152
33		3650	HF	✓	✓	✓	✓	✓	✓	V4.13
34		6021	HF	✓	✓	✓	✓	✓	✓	V03.87
35		6230	HF	✓	✓	✓	✓	✓	✓	V5.40
36		6230i	HF	✓	✓	✓	✓	✓	✓	V3.30
37		6820	HF	✓	✓	✓	✓	✓	✓	V04.25
38		6820a	HF	✓	✓	✓	✓	✓	✓	
39		6822	HF	✓	✓	✓	✓	✓	✓	V4.48
40		7370	HF	✓	✓	✓	✓	✓	✓	V 04.13
41		7380	HF	✓	✓	✓	✓	✓	✓	V03.80
42		7710	HF	✓	✓	✓	✓	✓	✓	V03.04.2
43		8800	HF	✓	✓	✓	✓	✓	✓	V03.60
44		8801	HF	✓	✓	✓	✓	✓	✓	V03.94
45		8910	HF	✓	✓	✓	✓	✓	✓	V04.02
46		N-GAGE	HF	✓	✓	✓	✓	✓	✓	V3.30

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✗ not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Version of phone software used to test/ Comments
47	Siemens	S55	HF	✓	✓	✓	✓	✓	✓	SW:91
48		SX1	HF	✓	✓	✓	✓	✓	✓	SW:14
49		S65	HF	✓	✓	✓	✗	✓	✓	SW:25
50		SK65	HF	✓	✓	✓	✗	✓	✓	SW:42
51		CX75	HF	✓	✓	✓	✗	✓	✓	SW:05
52		M75	HF	✓	✓	✓	✗	✓	✓	SW:05
53		S65v	HF	✓	✓	✓	✗	✓	✓	SW:25
54		SP65	HF	✓	✓	✓	✗	✓	✓	
55		EL71	HF	✓	✓	✓	✗	✓	✗	SW:31
56	Motorola	A 835	HF	✓	✓	✓	✓	✓	✓	TALINT_0_7232.07.02P
57		V500	HF	✓	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.10R_VR
58		V525	HF	✓	✓	✓	✓	✓	✓	TRIPLETS_G0B09.1DR_VR
59		V550	HF	✓	✓	✓	✓	✓	✓	R376_G_0E.65.26R
60		V551	HF	✓	✓	✓	✓	✓	✓	R47_G08_17.OFR01
61		V600	HF	✓	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.38R
62		V620	HF	✓	✓	✓	✓	✓	✓	R376_G_0E.65.25R
63		V3 RAZR	HF	✓	✓	✓	✓	✓	✓	R374_G_0E40.3CR
64		E1 ROKR	HF	✓	✓	✓	✓	✓	✓	R373_G_0E.30.42R
65		SLVR V270	HF	✓	✓	✓	✓	✓	✓	R3511_G_0A..50.1BR
66		V280	HF	✓	✓	✓	✓	✓	✓	R3511_G_0A..50.22BR
67		L7	HF	✓	✓	✓	✓	✓	✓	R4513_G_08.B7.54R_RB
68		C390	HF	✓	✓	✓	✓	✓	✓	R368_G_0B_AQ0_05I
69		E770v	HF	✓	✓	✓	✓	✓	✓	R25221_U85.83.E1P
70		E398	HF	✓	✓	✓	✓	✓	✓	-
71		E1070	HF	✓	✓	✓	✓	✓	✓	R25221LD_U_85.97.C3P
72		U6	HF	✓	✓	✓	✓	✓	✓	R478_G_08.83.76R_A
73	V635	HF	✓	✓	✓	✓	✓	✓	R474_G_08.48.24R_A	
74	Sony Ericsson	T68i	HF	✓	✓	✓	✓	✓	✓	R5D007
75		T68m	HF	✓	✓	✓	✓	✓	✓	R2B013
76		T39m	HS	✗	✗	✗	✗	✗	✓	R2G
77		T610	HF	✓	✓	✓	✓	✓	✓	R3C002
78		T616	HF	✓	✓	✓	✓	✓	✓	R1A0044
79		T630	HF	✓	✓	✓	✓	✓	✓	R7A011
80		R520m	HS	✗	✗	✗	✗	✗	✓	R2K
81		K600i	HF	✓	✓	✓	✓	✓	✓	R2AC001
82		K700i	HF	✓	✓	✓	✗	✓	✓	R2AY004
83		S700i	HF	✓	✓	✓	✗	✓	✓	R3C002
84		P910i	HF	✓	✓	✓	✓	✓	✓	R4A006
85		P990i	HF	✓	✓	✓	✓	✗	✓	CXC162037 R7A001
86		K750i	HF	✓	✓	✓	✓	✓	✓	R1A0044
87		W600i	HF	✓	✓	✓	✓	✓	✓	R7B046
88		W700i	HF	✓	✓	✓	✓	✓	✓	R1CA021
89		W800i	HF	✓	✓	✓	✓	✓	✓	R1L002
90		W810i	HF	✓	✓	✓	✓	✓	✓	R4DB005
91		W850i	HF	✓	✓	✓	✓	✓	✓	R1ED001
92		W900i	HF	✓	✓	✓	✓	✓	✓	R5BC004

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✗ not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Version of phone software used to test/ Comments
93	Sony Ericsson	W950i	HF	✓	✓	✓	✓	✗	✓	R9C001
94		D750i	HF	✓	✓	✓	✓	✓	✓	R1N035
95		Z600	HF	✓	✓	✓	✓	✓	✓	RE004
96		K610i	HF	✓	✓	✓	✓	✓	✓	
97		V630i	HF	✓	✓	✓	✓	✓	✓	
98		K800i	HF	✓	✓	✓	✓	✓	✓	
99		K510i	HF	✓	✓	✓	✗	✓	✓	R4CH003
100		Z520i	HF	✓	✓	✓	✗	✓	✓	R3F015
101		Z530i	HF	✓	✓	✓	✓	✓	✓	R6BA030
102		Z1010	HF	✓	✓	✓	✓	✓	✓	RG007
103		M600i	HF	✓	✓	✓	✗	✗	✓	R1B01
104		V800	HF	✓	✓	✓	✓	✓	✓	R1J002
105	Samsung	SGH-E720	HF	✓	✓	✓	✗	✓	✓	
106		SGH-D307	HF	✓	✓	✓	✓	✓	✗	
107		SGH-D500	HF	✓	✓	✓	✗	✓	✓	
108		SGH-D520	HF	✓	✓	✓	✗	✓	✗	
109		SGH-D600	HF	✓	✓	✓	✗	✓	✓	
110		SGH-D900	HF	✓	✓	✓	✗	✓	✗	
111	Panasonic	X70	HF	✓	✓	✓	✗	✓	✓	
112	Toshiba	TS921	HF	✓	✓	✓	✗	✓	✓	
113	Sharp	GX15	HF	✓	✓	✓	✗	✓	✓	
114		GX25	HF	✓	✓	✓	✗	✓	✓	
115		GX30i	HF	✓	✓	✓	✗	✓	✓	
116	HP	H 6340	HF	✓	✓	✓	✗	✓	✓	
117		HW 6510	HF	✓	✓	✓	✗	✓	✓	1.06.12GER
118		HW 6515	HF	✓	✓	✓	✗	✓	✓	1.01.00 WWE
119		HW 6915	HF	✓	✓	✓	✗	✓	✓	1.47.00 GER
120	SDA	I	HF	✓	✓	✓	✓	✓	✓	V4.21.1088
121		Music	HF	✓	✓	✓	✓	✓	✓	
122		II	HF	✓	✓	✓	✓	✓	✓	
123	Xphone	II	HF	✓	✓	✓	✓	✓	✓	2.037.21
124	I-mate	SP3	HF	✓	✓	✓	✓	✓	✓	V4.21.1088
125		SP3i	HF	✓	✓	✓	✓	✓	✓	
126		JAM	HF	✓	✓	✓	✗	✓	✓	V 1.03.00
127	SPV	C-500	HF	✓	✓	✓	✓	✓	✓	1337.0.32.0.03.18
128		C-600	HF	✓	✓	✓	✓	✓	✓	4.0.13.10_00.17.00
129		C-700	HF	✓	✓	✓	✓	✓	✓	1.06.00.00
130		M-500	HF	✓	✓	✓	✗	✓	✓	1.05.10
131		M-1000	HS	✗	✗	✗	✗	✗	✓	1.10.00
132		M-2000	HF	✓	✓	✓	✗	✓	✓	
133		M-5000	HF	✓	✓	✓	✗	✓	✓	
134	VPA	Compact	HF	✓	✓	✓	✗	✓	✓	1.05.00
135		III	HF	✓	✓	✓	✗	✓	✓	

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✗ not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Version of phone software used to test/ Comments
136	MDA	Compact	HF	✓	✓	✓	✗	✓	✓	
137		Compact II	HF	✓	✓	✓	✓	✓	✓	
138		II	HS	✗	✗	✗	✗	✗	✓	4.20.0
139		III	-	-	-	-	-	-	-	-
140		IV	HF	✓	✓	✓	✗	✓	✓	0.90.00
141	Qtek	9100	HF	✓	✓	✓	✓	✓	✓	1.6.7.1
142		9090	HF	✓	✓	✓	✗	✓	✓	1.06.00
143		8310	-	-	-	-	-	-	-	-
144		2020	HS	✗	✗	✗	✗	✗	✓	1.14.00
145		8020	HF	✓	✓	✓	✗	✓	✓	4.21.1088
146		8010	HF	✓	✓	✓	✗	✓	✓	
147		S100	HF	✓	✓	✓	✗	✓	✓	
148	XDA	II	HS	✗	✗	✗	✗	✗	✓	1.10.00
149		II i	HS	✗	✗	✗	✗	✗	✓	
150		II s	HF	✓	✓	✓	✗	✓	✓	
151		III	HF	✓	✓	✓	✗	✓	✓	1.10.00
152		Mini S	HF	✓	✓	✓	✓	✓	✓	01.09.10
153	BlackBerry	7290	HF	✓	✓	✓	✗	✓	✓	V3.8.0.105
154		7100g	HF	✓	✓	✓	✗	✓	✓	V4.0.0.140
155		7100v	HF	✓	✓	✓	✗	✓	✓	V4.0.2.16
156		7100t	HF	✓	✓	✓	✗	✓	✓	V3.8.0128
157		8100	HF	✓	✓	✓	✓	✓	✓	V4.2.0.64
158		8700g	HF	✓	✓	✓	✗	✓	✓	V4.1.0258
159		8707v	HF	✓	✓	✓	✗	✓	✓	V4.1.0.316
160		8800	HF	✓	✓	✓	✓	✓	✓	V4.2.1.43
161	Sagem	MyX-8	-	✗	✗	✗	✗	✗	✗	
162	Palm	Treo 650	HS	✗	✗	✗	✗	✗	✓	
163		Treo 680	HS	✓	✓	✓	✗	✓	✓	
164		Treo 750	HS	✓	✓	✓	✗	✓	✓	
165	LG	KG810	HS	✓	✓	✓	✗	✓	✗	
166		KG800	HS	✓	✓	✓	✗	✓	✗	
167	HTC	MTeor	HS	✓	✓	✓	✗	✓	✗	
<p>Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min), E-mail: infoline@bury.com, Internet: www.bury.com</p>										
<p style="text-align: center;"> ✓ working ✗ not working </p>										