



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
1	Motorola	A 835	HF	✓	✓	✓	✓	✓	TALINT_0_7232.07.02P
2		V500	HF	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.10R_VR
3		V525	HF	✓	✓	✓	✓	✓	TRIPLETS_G0B09.1DR_VR
4		V550	HF	✓	✓	✓	✓	✓	R376_G_0E.65.26R
5		V551	HF	✓	✓	✓	✓	✓	R47_G08_17.OFR01
6		V600	HF	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.38R
7		V620	HF	✓	✓	✓	✓	✓	R376_G_0E.65.25R
8		E1 ROKR	HF	✓	✓	✓	✓	✓	R373_G_0E.30.42R
9		V3 RAZR	HF	✓	✓	✓	✓	✓	R374_G_0E40.3CR
10		V3i	HF	✓	✓	✓	✓	✓	R479_G_08.B4.85R
11		SLVR V270	HF	✓	✓	✓	✓	✓	R3511_G_0A..50.1BR
12		V280	HF	✓	✓	✓	✓	✓	R3511_G_0A..50.22BR
13		L7	HF	✓	✓	✓	✓	✓	R4513_G_08.B7.54R_RB
14		C390	HF	✓	✓	✓	✓	✓	R368_G_0B_AQ0_05I
15		E770v	HF	✓	✓	✓	✓	✓	R25221_U_85.83.E1P
16		E550	HF	✓	✓	✓	✓	✓	
17		E1070	HF	✓	✓	✓	✓	✓	R25221LD_U_85.97.C3P
18		U6	HF	✓	✓	✓	✓	✓	R478_G_08.83.76R_A
19		V635	HF	✓	✓	✓	✓	✓	R474_G_08.48.24R_A
20	Nokia	6103	HF	✓	✓	✓	✓	✓	V04.90
21		6131	HF	✓	✓	✓	✓	✓	V03.70
22		6270	HF	✓	✓	✓	✓	✓	V03.66
23		6280	HF	✓	✓	✓	✓	✓	V4.25
24		6288	HF	✓	✓	✓	✓	✓	V05.92
25		6234	HF	✓	✓	✓	✓	✓	V3.50
26		E50	HF	✓	✓	✓	✓	✓	V06.27.1.0
27		E60	HF	✓	✓	✓	✓	✓	V.0610.02.15
28		E61	HF	✓	✓	✓	✓	✓	V. 3.0633.09.04
29		E65	HF	✓	✓	✓	✓	✓	V 1.0633.18.01
30		E70	HF	✓	✓	✓	✓	✓	V1.0610.05.06
31		6300	HF	✓	✓	✓	✓	✓	V 04.70
32		6310	HF	✓	✓	✓	✓	✓	V5.10
33		6310i	HF	✓	✓	✓	✓	✓	V5.51
34		9300	HF	✓	✓	✓	✗	✓	V4.53
35		9300i	HF	✓	✓	✓	✗	✓	V 05.50(00)
36		9500	HF	✓	✓	✓	✗	✓	V4.44
37		6600	HF	✓	✓	✓	✓	✓	V3.42.1
38		3230	HF	✓	✓	✓	✓	✓	V3.0505.2
39		3250	HF	✓	✓	✓	✓	✓	V03.24
40		5500	HF	✓	✓	✓	✓	✓	V 03.18
41		6680	HF	✓	✓	✓	✓	✓	V3.04.11
42		6681	HF	✓	✓	✓	✓	✓	V3.10.6
43		N70	HF	✓	✓	✓	✓	✓	V2.0536.02
44		N71	HF	✓	✓	✓	✓	✓	V 2.0613.1.12.1
45		N73	HF	✓	✓	✓	✓	✓	V2.0628.0.0.1
46		N90	HF	✓	✓	✓	✓	✓	V5.0607.7.3
47		N91	HF	✓	✓	✓	✓	✓	V1.11.003

Bury GmbH &amp; Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

 E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working      ✗ not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
48	Nokia	N93	HF	✓	✓	✓	✓	✓	V10.0.025
49		N80	HF	✓	✓	✓	✓	✓	V 3.0617.0.6
50		6630	HF	✓	✓	✓	✓	✓	V2.39.152
51		3650	HF	✓	✓	✓	✓	✓	V4.13
52		6021	HF	✓	✓	✓	✓	✓	V03.87
53		6151	HF	✓	✓	✓	✓	✓	V03.56
54		6230	HF	✓	✓	✓	✓	✓	V5.40
55		6230i	HF	✓	✓	✓	✓	✓	V3.30
56		6820	HF	✓	✓	✓	✓	✓	V04.25
57		6820a	HF	✓	✓	✓	✓	✓	
58		6822	HF	✓	✓	✓	✓	✓	V4.48
59		7370	HF	✓	✓	✓	✓	✓	V 04.13
60		7380	HF	✓	✓	✓	✓	✓	V03.80
61		7710	HF	✓	✓	✓	✓	✓	V03.04.2
62		8800	HF	✓	✓	✓	✓	✓	V03.60
63		8801	HF	✓	✓	✓	✓	✓	V03.94
64		8910	HF	✓	✓	✓	✓	✓	V04.02
65		N-GAGE	HF	✓	✓	✓	✓	✓	V3.30
66	Siemens	S55	HF	✓	✓	✓	✓	✓	SW:91
67		SX1	HF	✓	✓	✓	✓	✓	SW:14
68		S65	HF	✓	✓	✓	✗	✓	SW:25
69		SK65	HF	✓	✓	✓	✗	✓	SW:42
70		CX75	HF	✓	✓	✓	✗	✓	SW:05
71		M75	HF	✓	✓	✓	✗	✓	SW:05
72		S65v	HF	✓	✓	✓	✗	✓	SW:25
73		SP65	HF	✓	✓	✓	✗	✓	
74	EL71	HF	✓	✓	✓	✗	✓	SW:31	
75	Sony Ericsson	T68i	HF	✓	✓	✓	✓	✓	R5D007
76		T39m	HS	✓	✗	✗	✗	✗	R2G
77		T610	HF	✓	✓	✓	✓	✓	R3C002
78		T616	HF	✓	✓	✓	✓	✓	R1A0044
79		T630	HF	✓	✓	✓	✓	✓	R7A011
80		R520m	HS	✓	✗	✗	✗	✗	R2K
81		K600i	HF	✓	✓	✓	✓	✓	R2AC001
82		K700i	HF	✓	✓	✓	✗	✓	R2AY004
83		S700i	HF	✓	✓	✓	✗	✓	R3C002
84		P910i	HF	✓	✓	✓	✓	✓	R4A006
85		P990i	HF	✓	✓	✓	✓	✗	CXC162037 R7A001
86		K750i	HF	✓	✓	✓	✓	✓	R1A0044
87		W600i	HF	✓	✓	✓	✓	✓	R7B046
88		W700i	HF	✓	✓	✓	✓	✓	R1CA021
89		W800i	HF	✓	✓	✓	✓	✓	R1L002
90		W810i	HF	✓	✓	✓	✓	✓	R4DB005
91		W850i	HF	✓	✓	✓	✓	✓	R1ED001
	W900i	HF	✓	✓	✓	✓	✓	R5BC004	

Bury GmbH &amp; Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

 E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)


working



not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
93	Sony Ericsson	W950i	HF	✓	✓	✓	✓	✗	R9C001
94		D750i	HF	✓	✓	✓	✓	✓	R1N035
95		Z600	HF	✓	✓	✓	✓	✓	RE004
96		Z1010	HF	✓	✓	✓	✓	✓	RG007
97		K610i	HF	✓	✓	✓	✓	✓	
98		V630i	HF	✓	✓	✓	✓	✓	
99		K800i	HF	✓	✓	✓	✓	✓	
100		K510i	HF	✓	✓	✓	✗	✓	R4CH003
101		Z520i	HF	✓	✓	✓	✗	✓	R3F015
102		Z530i	HF	✓	✓	✓	✓	✓	R6BA030
103		M600i	HF	✓	✓	✓	✗	✗	R1B01
104		V800	HF	✓	✓	✓	✓	✓	R1J002
105	Samsung	SGH-E720	HF	✓	✓	✓	✗	✓	
106		SGH-D307	HF	✓	✓	✓	✗	✓	
107		SGH-D500	HF	✓	✓	✓	✗	✓	
108		SGH-D520	HF	✓	✓	✓	✗	✓	1.0c
109		SGH-D600	HF	✓	✓	✓	✗	✓	
110		SGH-D900	HF	✓	✓	✓	✗	✓	D900E.05
111		SGH-X820	HF	✓	✓	✓	✗	✓	0.3b
112	Panasonic	X70	HF	✓	✓	✓	✗	✓	
113	Toshiba	TS921	HF	✓	✓	✓	✗	✓	
114	Sharp	GX15	HF	✓	✓	✓	✗	✓	
115		GX25	HF	✓	✓	✓	✗	✓	
116		GX30i	HF	✓	✓	✓	✗	✓	
117	HP	H6340	HF	✓	✓	✓	✗	✓	
118		HW6510	HF	✓	✓	✓	✗	✓	1.06.12GER
119		HW6515	HF	✓	✓	✓	✗	✓	1.01.00 WWWE
120		HW6915	HF	✓	✓	✓	✗	✓	1.01.00 GER
121	Sda	I	HF	✓	✓	✓	✓	✓	V4.21.1088
122		Music	HF	✓	✓	✓	✓	✓	
123		II	HF	✓	✓	✓	✓	✓	
124	Xphone	II	HF	✓	✓	✓	✓	✓	2.037.21
125	I-mate	SP3	HF	✓	✓	✓	✓	✓	V4.21.1088
126		SP3i	HF	✓	✓	✓	✓	✓	
127		JAM	HF	✓	✓	✓	✗	✓	V 1.03.00
128	SPV	C-500	HF	✓	✓	✓	✓	✓	1337.0.32.0.03.18
129		C-600	HF	✓	✓	✓	✓	✓	4.0.13.10_00.17.00
130		C-700	HF	✓	✓	✓	✓	✓	1.06.00.00
131		M-500	HF	✓	✓	✓	✗	✓	1.05.10
132		M-2000	HF	✓	✓	✓	✗	✓	
133		M-5000	HF	✓	✓	✓	✗	✓	
134	VPA	Compact	HF	✓	✓	✓	✗	✓	1.05.00
135		III	HF	✓	✓	✓	✗	✓	

Bury GmbH &amp; Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✗ not working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
136	MDA	Compact	HF	✓	✓	✓	✗	✓	
137		Compact II	HF	✓	✓	✓	✓	✓	
138		II	HS	✓	✗	✗	✗	✗	4.20.0
139		III	HF	✓	✓	✓	✗	✓	
140		IV	HF	✓	✓	✓	✗	✓	0.90.00
141	Q-tek	9090	HF	✓	✓	✓	✗	✓	1.06.00
142		9100	HF	✓	✓	✓	✓	✓	1.6.7.1
143		2020	HS	✓	✗	✗	✗	✗	1.14.00
144		8310	HF	✓	✓	✓	✗	✓	
145		S100	HF	✓	✓	✓	✗	✓	
146	XDA	II	HS	✓	✗	✗	✗	✗	1.10.00
147		II i	HS	✓	✗	✗	✗	✗	
148		II s	HS	✓	✓	✓	✗	✓	
149		III	HF	✓	✓	✓	✗	✓	1.10.00
150		Mini S	HF	✓	✓	✓	✓	✓	01.09.10
151	BlacBerry	7290	HF	✓	✓	✓	✗	✓	V3.8.0.105
152		7100g	HF	✓	✓	✓	✗	✓	V4.0.0.140
153		7100v	HF	✓	✓	✓	✗	✓	V4.0.2.16
154		7100t	HF	✓	✓	✓	✗	✓	V3.8.0128
155		8100	HF	✓	✓	✓	✓	✓	V4.2.0.64
156		8700g	HF	✓	✓	✓	✗	✓	V4.1.0258
157		8707v	HF	✓	✓	✓	✗	✓	V4.1.0.316
158		8800	HF	✓	✓	✓	✓	✓	V4.2.1.43
159	Palm	Treo 650	HS	✓	✗	✗	✗	✗	
160		Treo 680	HS	✓	✓	✓	✗	✓	
161		Treo 750	HS	✓	✓	✓	✗	✓	
162	LG	KG810	HS	✓	✓	✓	✗	✓	
163		KG800	HS	✓	✓	✓	✗	✓	
164	HTC	MTeor	HS	✓	✓	✓	✗	✓	Build 14927.2.2.0 Radio 0.72.01

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),  
E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working      ✗ not working