



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries	Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
							SIM Card	Received calls	Missed calls					
1	Motorola	V500	HF	✓	✓					✓	✓	✓	✓	/ TRIPLETS_G_0B.09.1DR_VA
2		V525	HF	✓	✓					✓		✓		/ TRIPLETS_G_0B.09.1DR_VA
3		V550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.26R
4		V551	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R47_G_0B.17.0FR_01
5		V557	HF	✓	✓					✓		✓		/ R4512_G_0B.28.40R
6		V635	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R474_G_0B.48.24R_A
7		V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.25R
8		ROKR E1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R373_G_0E.30.42R
9		L2	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.53.15R
10		L6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.50.22R
11		L7	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4513_G_0B.7.5DR_RB
12		V3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R374_G_0E.40.79R
13		V3i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_0B.84.85R
14		K1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4527_G0B.22.07R
15		U6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478_G_0B.83.76R_A
16		C390	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R368_G_0B.A0.0FR
17		E1000	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478_G_0B.83.76R_A
18		Z3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4527_G0B.01.02R
19		1070	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.C3P
20		E770v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221_U_85.83.E1P
21	Nokia	6820a	HF	✓	✓					✓	✓	✓	✓	/ 4.25
22		6230i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.88
23		6310	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.10
24		6310i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 5.60
25		6230	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 05.24
26		6233	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.70
27		6234	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.91
28		E50	HF	✓	✓									/ 06.41.3.0
29		E60	HF	✓	✓									/ 2.0618.06.05
30		E61	HF	✓	✓									/ 2.0618.06.05
31		E65	HF	✓	✓									/ 1.0633.18.01
32		E70	HF	✓	✓									/ 2.0618.07.10
33		N70	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 5.0638.3.0.1
34		N73	HF	✓	✓									/ 2.0628.0.0.1
35		N91	HF	✓	✓									/ 1.11.003
36		N93	HF	✓	✓									/ 10.0.025
37		N71	HF	✓	✓									/ 2.0613.1.12.1
38		N90	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 5.0607.7.3
39		N80-1	HF	✓	✓									/ 3.0617.0.6
40		8910	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 04.02.25
41		6822a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.52
42		6021	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 04.90
43		6670	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 6.0522.0
44		6680	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 2.04.15
45		6681	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.10.6

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working

✓\* Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries	Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Received calls	Missed calls	Dialled numbers					
46	Nokia	6630	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 2.39.152
47		9300	HF	✓	✓					✓	✓	✓		/ 5.22
48		9300i	HF	✓	✓					✓	✓	✓		/ 5.50
49		6270	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 03.66
50		6103	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 04.90
51		6682	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.01.1
52		7280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.22
53		7710	HF	✓	✓					✓	✓	✓		/ 3.04.2
54		8801	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.94
55		8800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.10
56		6280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 3.65
57		6288	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 5.92
58		6600	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.42.1
59		5500	HF	✓	✓									/ 03.18
60		6125	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 03.71
61		6111	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 03.58
62		6151	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 3.56
63		6131	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 3.70
64		3250	HF	✓	✓									/ 3.24
65		3230	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.0505.2
66	Sony-Ericsson	K610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1BA022 prgCXC1250536_V
67		K700i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R2L001 prgCXC 125821_EU_1_C
68		S700i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3C002 PRGCXC125936_EU_2_T
69		D750i	HF	✓	✓	✓	✓	✓	✓	✓	✓			/ R1AA008 PRG CXC125952_EU_1_CLR1AA008
70		V800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1J002 PRG CXC 125839_EU_1_VA
71		W550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4BA041
72		W600i	HF	✓	✓					✓	✓	✓		/ R7B046
73		W800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1L002 PRG CXC1250092_EU_1_CA R1L002
74		W810i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4DB005 prg CXC1250320
75		W850i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001 PRGCXC1250201_Vodafone_CYR1E
76		W900i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R5BC004
77		W950i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R9C001 prg CXC162037
78		P990i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R4F01 CXC 162058
79		V630i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1CE001
80		V800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ P1J002 prg CXC125839_EU_1_VA
81		K750i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1C004 prgCXC 1250035_EU_2_CL
82		K800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1ED001
83		T610i	HF	✓	✓					✓	✓	✓		/ R3C002
84		T630i	HF	✓	✓					✓	✓	✓		/ R7A011
85		K600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2AC001 CXC1250076.EU.6_MI
86		K510i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4CH003 1250231_GENERIC_C0
87		Z610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1ED001
88		Z600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2E004 CXC125731_EU_7
89		Z1010	HF	✓	✓	✓	✓	✓	✓	✓	✓			/ R1G007 PRG CXC125432_EU_1_V
90		P800	HS	✓	✓									
91		P900	HS	✓	✓									
92		Z530i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R6BA030 PRG 1250454_GENERIC_MUR6BA030
93		M600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ R1B01

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working

✓\* Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries	Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Received calls	Missed calls	Dialled numbers					
94	Siemens	CX75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:17	
95		S65v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:25	
96		SK65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:50	
97		S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 50	
98		SP 65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 47	
99		M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23	
100		S55	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:91	
101		BenQ M81	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:46	
102		BenQ S68	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23	
103		Samsung	E720	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 1.0g
104	X820		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ Rev. 0.3b	
105	D520		HF	✓	✓	✓				✓	✓		/ SW: 1.0C	
106	D500		HF	✓	✓								/ EG001.08	
107	D600		HF	✓	✓								/ TG001.06	
108	D800		HF	✓	✓	✓	✓	✓	✓	✓	✓		/ 1.1	
109	E900		HF	✓	✓	✓	✓	✓	✓	✓	✓		/ 1.0a	
110	D900		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ D900E.05	
111	D307		HF	✓	✓								/ 06	
112	D357		HF	✓	✓	✓	✓	✓	✓	✓	✓		/ 1.4	
113	E380		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ FE380.02	
114	P900		HF	✓	✓	✓	✓	✓	✓	✓	✓		/ Rev 1.1	
115	BlackBerry	7100	HF	✓	✓						✓		/ 4.02.16	
116		7130	HF	✓	✓								/ 4.10.327	
117		8100	HF	✓	✓								/ 4.2.0.64	
118		8707	HF	✓	✓	✓				✓	✓	✓	/ 4.1.0.275	
119	HTC	MDA	HF	✓	✓	✓	✓	✓	✓					
120		Xda Trion	HF	✓	✓	✓	✓	✓	✓				/ 1.25.207.1	
121		TyTN	HF	✓	✓	✓	✓	✓	✓				/ 0.93.03	
122		MDA II	HS	✓	✓								/ 1.72.01GER	
123	LG	KG800	HF	✓	✓									
124		KG810	HF	✓	✓									
125	SHARP	GX15	HF	✓	✓								/ A07-0070210	
126		GX25 GZ200	HF	✓	✓									
127		GX30i	HF	✓	✓								/ A02-010-0041	
128	PalmOne	Treo 650	HF	✓	✓		✓	✓	✓	✓	✓	✓	/ TREQ650-1.02-CNG Firmware:1.51	
129		Treo 680	HF	✓	✓		✓	✓	✓	✓	✓	✓	/ TREQ-680-1.00A/3102-	
130		Treo 700p	HF	✓	✓		✓	✓	✓	✓	✓	✓	/ 2106/105	
131		Treo 750v	HF	✓	✓		✓	✓	✓	✓	✓	✓	/ TREQ750-1.14-VFD	

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)